



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD 2023/07/19	Report Number	20230719-WMSC-RRD-2
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name
Rail Agency Department	SAFE/OEP	Contact Information	
Inspection Location	Woodley Park A04 2622 Connecticut Avenue, NW Washington, D.C.		

Inspection Summary

Inspection Activity #	1
Activity Code	EMGT-GEN-RR
Inspection Units	1
Inspection Subunits	0
Defects (Number)	10
Recommended Finding	No
Remedial Action Required¹	Yes
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Inspection Subject	Woodley Park Station Inspection Report					Activity Code	EMGT-GEN-RR			
Job Briefing Employee Name/Title	N/A	Accompanied Inspector?	No		Out Brief Conducted	No		Time		Outside Shift	No	
Related Reports	Previous Woodley Park Station Reports. Emergency Management and Fire Life Safety Audit. Industry Safe Report 5400, 5440 - First Quarter Record Review.		Related CAPS / Findings			WMSC-22-C0175 WMSC-22-C0174 WMSC-22-C0178						
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP			Standard		Other / Title			Checklist Reference		
	NFPA 130 International Building Code: 901.6 Maintain Fire Protection System. 1031.4 Exit Signs. 509.1 Signs Required for Fire Protected Rooms.										Metrorail Station Checklist	
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A	
			X									
Line(s) & Track Number	Woodley Park A04 2622 Connecticut Avenue, NW Washington, D.C.				Chain Marker and/or Station(s)			From		To		
								Station Limits		Station Limits		
Vehicles	Head Car Number		Number of Cars		Equipment		Fire Life Safety Equipment.					
	N/A		N/A									
Description	The WMSC inspector conducted a first quarter record reviews of the Woodley Park FLS Annual Inspection Reports. This record review consists of 3 randomly chosen stations. 1. Farragut North Industry Safety Report # 5400 2. Woodley Park Industry Safety Report # 5420 3. Judiciary Sq Industry Safety Report # 5440 Each report shows similarities in deficiencies in maintaining Fire Life Safety items (CAPs provided in reference section).							Number of Defects		10		
								Recommended Finding?		No		
								Remedial Action Required?		Yes		
								Recommended Reinspection?		Yes		
Remedial Action	Assign a work order to the appropriate department and the mitigation action is monitored until completion. Take action to mitigate any immediate safety hazard.											

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature	Date 2023/07/19
Inspector in Charge's Name Richard David	Inspection Team N/A