

Inspection Form

Washington Metrorail Safety Commission

Date

Agency/Department Information

Inspection Date		YYYY/MM/DD	Report Number	20230917-WMSC-RRD-1		
Inspection Date		2023/09/19		20250917-WWSC-RRD-1		
Rail Agency Name	Washi	ington Metropolitan Area Transit Authority	Rail Agency Department	Name		
Rail Agency Department	SAFE		Contact Information			
Inspection Location	Capit	tol South Metro Station 355 First St. Washington DC 20003				
Inspection Summary						
Inspection Activity #		1				
Activity Code		EMGT-TNG-OBS				
Inspection Units		1				
Inspection Subunits		0				
Defects (Number)		0				

No No

No

Recommended Finding Remedial Action Required¹ Recommended Reinspection

Inspector in Charge's Signature

Activity Summaries Inspection Activity Inspection Subject **OEP** Exercise Activity Code EMGT-TNG-OBS 1 # Job Briefing Yes - Exercise Director, Actor Out Brief Outside Employee Controller Accompanied Inspector? No Yes Time Yes Conducted Shift Name/Title Previous OEP Planning and **Related Reports Related CAPS / Findings** Exercise reports. Rule or SOP Other / Title Checklist Reference Ref Standard **Related Rules**, **OEP** Exercise SOPs, Standards, or Handbooks Agency Safety Plan Other Controller and Evaluator handbook WMSC Main Yard Station occ **RTA Facility** At-grade Tunnel Elevated N/A Track Office Inspection Location Track Type Х То From Line(s) & Track Capitol South Metro Station 355 First St. Chain Marker and/or Number Washington DC 20003 Station(s) 114+04 108+04 Head Car Number Number of Cars Station (for the scenario). Railcars (for the scenario). WSAD (RWP set Vehicles Equipment up). Hot Stick (RWP set up). PPE The WMSC conducted an observation of one of the Office of Emergency Preparedness Number of Defects 0 annual drills to ensure compliance with the Agency Safety Plan training requirements. **Recommended Finding?** No Description **Remedial Action Required?** No **Recommended Reinspection?** No **Remedial Action**

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

		2023/09/19
Inspector in Charge's Name	Inspection Team	
Richard David	Darrell Braxton Bruce Walker Kathy Silbaugh Tiffany Minor	