

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY/MM/DD	Daniest Normalism	20230928-WMSC-LBW-1					
Inspection Date	2023/09/28	Report Number	20230928-WINISC-LBW-1					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	Roadway Worker Protection (RWP)	Contact Information						
Inspection Location	Rhode Island Ave - Brentwood Station, Brookland- Catholic University Station, Fort Totten Station							

Inspection Summary

Inspection Activity #	1
Activity Code	PI-SAFE-QAI
Inspection Units	1
Inspection Subunits	0
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Insi	ection Subject Advanced Mobi			d Mobile	Flagging Pro	tection	Activity Code			PI-SAFE-QAI				
Job Briefing Employee Name/Title	With Rail Op Center	/ith Rail Operation Control Acc			Accompanied Inspector?			Out Brief Conducted	No Time		08:00 AM		Outside Shift	Yes		
Related Reports	NA			Related C	APS / Findin	gs		NA								
Related Rules,	Ref Rule o			e or SOP Standard				Other / Title Chec					cklist Reference			
SOPs, Standards, or Other	NA	NA SOP 4 Flaggi			40 Advanced Mobile ging				NA				NA			
Inspection Location	Main Track	Yard	Station	occ	RTA Facility WMSC Office Track Type		Track Type	At-grade Tunno		iel Elevate		ted	i N/A			
	Χ		Х						Х							
Line(s) & Track	Rhode Island				Chain Ma	rker and/	or		From				То			
Number	Brookland C Totten Statio		iversity St	ation, Fort	Station(s)			na			na					
Vehicles	Head Car	Number	N	Number of Cars Equipment												
Venicies																
	The WMSC Inspectors conducted an unannounced Risk Based Inspection of the Advanced Mobile Flagger (AMF) protection on the Red Line. The inspectors contacted the							Number of Defects						0		
	Rail Operations Control Center (ROCC) prior to inspection to perform a job briefing and									Recommended Finding?					No	
	request the location of all crews working on the Bravo Line. Additionally, the Rail Traffic									Remedial Action Required?					No	
Description	Controller (RTC) was informed that all inspection activities would take place either on the train or on the platform. The inspectors would not be accessing the roadway during this inspection. The scope of this inspection was Metrorail's implementation of their AMF procedures from the platform, roadway worker and the train operator. Advanced Mobile Flagging protection was observed at the Rhode Island Ave - Brentwood Station, Brookland Catholic University Station, and the Fort Totten Station. Upon arrival at each station, the inspection team observed the AMF personnel in the performance of duties from a distance. The inspectors next approached each AMF verified all required safety equipment and observed the AMF in the performance of their duties and interaction with the rail vehicle operators. The inspection team boarded several trains and observed the Train Operator (TO) from outside of the operators' cab area. All TO's we observed following all AMF speed and train horn procedures. Upon observation of wayside personnel, the TO reduced speed and responded correctly to all received hand signals. Upon arriving at each station platform, the TO were observed dollowing all platform servicing procedures. All wayside personnel were observed utilizing all required personal protective equipment (PPE), and watchman lookout personnel observed were in the correct position and providing the correct hand signals to the									(es						
Remedial Action	vehicle oper	ators.														



Inspection Form

Form WMSC-IR-1
Washington Metrorail Safety Commission

Photos:			
20230928_104450.heic			
20220020 1110251 :			
20230928_111925.heic			
1			
The rail transit agency must provide WMSC v	with the necessary evidence (e.g. maintenance work order system records, p	hotos, documentation, records, data, or other e	vidence) to close out the Remedial
Action. Closeout of Remedial Actions may also	be subject to ongoing WMSC verification inspections to ensure corrections	are sufficient and effective.	
Inspector in Charge's Signature			Date
			2023/09/28
Inspector in Charge's Name	Inspection Team		
LeBon Bruce Walker	Darrell Braxton		