

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY/MM/DD	Donart Number	20231102-WMSC-RRD-1				
Inspection Date	2023/11/08	Report Number	20721107-MINI2C-UVD-1				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	MICC/SAFE	Contact Information					
Inspection Location	Arlington County Fire Station 6 6950 Little Falls Road Arlington VA, 22213						

Inspection Summary

Inspection Activity #	1
Activity Code	EMGT-TNG-OBS
Inspection Units	1
Inspection Subunits	0
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #	1	Ins	pection S	ubject	t WMATA/Arlington FD Tabletop Exercise			Activity Code			EMGT-TNG-OBS				
Job Briefing Employee Name/Title	Yes			Accompan	Accompanied Inspector?			Out Brief Conducted	Yes Time				Outside Shift		No
Related Reports	Previous Ta	bletop Exe	Related CAPS / Findings												
	Ref		R	ule or SOP			Standard		Other / Title				Checklist Reference		
Related Rules, SOPs, Standards, or Other	Homeland S Exercise and Program (HS	d Evalúatio		ncident Mana ramework	gement		Plan/Emer	Plan/Training					Facilitator Handbook Situation Manual Hot Wash/Feedback Form		
Inspection Location	Main Track	Yard	Statio	on OCC	RTA Facility		WMSC Office	Track Type	At-grade		Tunn	Tunnel		ted	N/A
			Х												Χ
Line(s) & Track	Arlington Co	,			Chain Ma	rker and	or Station(s)		From			То			
Number	Falls Road A	rlington V	٩, 22213		Chairina	- Cr unu,	01 34441011(3)	N/A	N/A						
Vehicles	Head Car	Number		Number of 0	Number of Cars			ant Handbook and		nd written material Audio/Visual					
	N/	'A	N/A	N/A Equipme			Hallubook allu		ia writter material Addio/ visual						
	The WMSC inspector conducted an observation of WMATA's/Arlington Tabletop Exercise. This TTX is in preparation for the Full-Scale Exercise. The accommodations were adequate hosted by Arlington County Fire Department. There was excellent interaction/participation by all stakeholders. Questions and answer session concluded								Number of Defects					0	
Description									Recommended Finding?					N	0
Description									Remedial Action Required?					N	o
	the exercise	and there	wasah	notwash with	a feedbac	k form.			Recommended Reinspection?			N	No		
Remedial Action															



Inspection Form

Form WMSC-IR-1
Washington Metrorail Safety Commission

Photos:



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action. Closeout of Remedial Actions m	iay also be subject to ongoing WMSC verification inspections to ensure corrections are suf	icient and effective	
Inspector in Charge's Signature			Date 2023/11/08
Inspector in Charge's Name Richard David	Inspection Team N/A		